

Basic Safety Rules

- 1. Know the location of all fire extinguishers.

 Know which extinguisher contains the right fire-fighting agent for each type of fire:
 - Class A wood & paper products
 - Class B flammable liquids
 - Class C electrical equipment
- Always wear eye protection. Even if you're not doing anything, other people are and a flying piece of wood or metal from their job can easily injure you.
- 3. Always clean up sawdust; it can be just as slippery as a spilled liquid, oil or grease.
- 4. Don't use screwdrivers as chisels or pry bars.
- 5. Never carry sharp tools in your pockets.
- Wear suitable clothing. Remove or fasten loose clothing, neckties, or jewelry. Roll loose sleeves to elbows.
- 7. Don't work with oily or greasy hands.
- Plan your work before you start. If you're cutting a large piece of wood, ask for help before you start cutting. Don't wait until you're in trouble.
- Secure all small work & short work in a vise or with a clamp.
- 10. Don't pry or hammer with a file. It may shatter.

- 11. Securely fasten long hair or hair styles that could create a hazard, or wear a hair cover.
- 12. Handle all sheet metal carefully. A metal edge can be as sharp as the tool which cut it.
- 13. Handle sharp-edged tools & pointed tools with care. Carry pointed tools with the points down. Carry all tools so they don't pose a danger to the people around you.
- 14. Report any equipment that doesn't seem to work properly.
- 15. Report all injuries, no matter how slight, when they occur. Even if it doesn't seem serious, it can become infected days later if not properly treated.
- 16. Wear the proper safety equipment for the job.
- 17. Keep the aisles clear. Don't leave extension cords where someone could trip over them. If they must go across an aisle, fasten them to the floor.
- 18. Place oily rags & other combustible materials in approved metal containers.
- 19. Cut away from yourself when you use chisels and other edged tools.
- 20. Don't distract or crowd around people while they're working.